| ECS Configuration Change Request | | | | | | | Page 1 of | f | Pag | ge(s) |
|---|----------------|--------------|--|-------------|-------------------|--|-----------------|---------------------------|--|--------------|
| 1. Originato | r | 2. Log Date: | | 3. CCR #: | | 4. Rev: | 5. Tel: | | 6. Rm #: | 7. Dept. |
| Darryl M. Was | hington | 10/08/02 | | 02-0888 | | _ | X0734 | | 2079 | SE |
| 8. CCR Title: Back-out BDSpro 2.4 to version 2.3 in the PVC | | | | | | | | | | |
| 9. Originator Signature/Date | | | | | 10. Class | | 11. Type: 12 | | 2. Need Date: 10/11/2002 | |
| Darryl M. Washington /s/ 10/8/02 | | | | | IN | | CCR | | | |
| 13. Office Manager Signature/Date | | | | | 14. Category | | £:11 | | 5. Priority: (If "Emergency" ill in Block 27). | |
| Carolyn Whitaker /s/ 10/8/02 | | | | | Initial E | seline Doc. | Routine | | | |
| • • • | | | | | | 7. Schedule 18. CI(s) Affected: npact: | | | | |
| 19. Release Affected by this Change: 20. Date due | | | | | | | | | | |
| 5A | | | | | None - Under 100K | | | | | |
| 22. Source Reference: □NCR (attach) □Action Item □Tech Ref. □GSFC ☑Other: | | | | | | | | | | |
| 23. Problem: (use additional Sheets if necessary) An upgrade to BDSpro to version 2.4 w/security patch (Patch 4713) encounterd problems at GSFC DAAC and the PVC. Due to the complexity of the problem, the application upgrade was reversed to the original version (BDSpro 2.3) for the DAAC to remain operational. Reversing the upgrade to the previous version, still leaves security vulnerability in version 2.3. The recommended fix from SGI for version 2.3, was to upgrade to version 2.4 (with the patch). Since the 2.4 version has problems, SGI has agreed to provide a patch for version 2.3. The patch must be tested before going into operational DAAC. To accomplish this, the PVC must be at v2.3 | | | | | | | | | | |
| 24. Proposed Solution: (use additional sheets if necessary) Uninstall BDSpro 2.4 from all SGI machines in the PVC, and re-install BDSpro 2.3. Patch will be installed upon receipt from SGI. | | | | | | | | | | |
| 25. Alternate Solution: (use additional sheets if necessary) | | | | | | | | | | |
| 26. Consequences if Change(s) are not approved: (use additional sheets if necessary) | | | | | | | | | | |
| 27. Justification for Emergency (If Block 15 is "Emergency"): | | | | | | | | | | |
| 28. Site(s) Affected: DF DVC VATC EDC GSFC LaRC NSIDC SMC AK JPL DEOC DIDG Test Cell Other | | | | | | | | | | |
| 29. Board Comments: | | | | | 30. Work As | | Work Assigned 1 | ed To: 31. CCR Closed Dat | | Closed Date: |
| | | | | | | | - | | | |
| 32. EDF/SCD | | | Disp | osition: Ar | proved | App/Co | om. Disapproved | W b | ithdraw Fw | d/ESDIS ERB |
| Byron V. Pete | ers /s/ 10 | 0/9/02 | | Fv | vd/ECS | | | | | |
| 33. M&O CC | 3 Chair (Sign | n/Date): | Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS | | | | | | | |
| 34. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB | | | | | | | | | | |
| 34. LOG COE | Jilali (Jigili | , Datoj. | Fwd/ESDIS | | | | | | | |

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O

ADDITIONAL SHEET

CCR #: 02-0888 Rev: — Originator: Darryl M. Washington

Telephone: X0734 Office: 2079

Title of Change: Back-out BDSpro 2.4 to version 2.3 in the PVC

Problems were encountered while trying to upgrade SGI BDSpro 2.3. The upgrade verison (version 2.4) displayed problems at both GSFC DAAC (memory allocation problems), and EDF PVC (server core dumps) which prompted the removal of the 2.4 version at GSFC. As reported, a security vulnerabilty exist in BDSpro, that was fixed with an upgrade to 2.4 and a security patch (Patch 4713). SGI has been working to resolve the problem w/version 2.4, but GSFC has requested a fix for version 2.3. As version 2.3 is a proven product, and has been running for a while, GSFC DAAC is willing to accept this risk of running briefly with 2.3 until a patch can be provided. SGI has promised a fix for version 2.3 in approximately 2 weeks. This patch will be tested first in the Landover PVC. To accomplish this testing, BDSpro version 2.4 must be de-installed, and version 2.3 re-installed. BDSpro version 2.4 will be removed following hosts in the PVC:

(BDSpro 2.3 will be re-installed on these same host machines.)

p0acg05

p0drg01

p0drg04

p0spg01

p0spg07

p0icg01 p0dig06

p0wkg01

p0teg01

CM01AJA00 Revised 8/2/02

ECS